# valspar

# paintandcolor.com

The molecules on the surface of Valspar's fluoropolymer coating systems are so tightly bound together that they don't want to react with anything. Their slick surface helps make them resistant to many elements found in the environment such as air pollution, acid rain, and general airborne dirt.

Although Valspar factory-applied finishes are extremely durable, a periodic cleaning to remove buildups of resins and other residue is a good idea to extend coating life. A variety of methods for removal of surface deposits are available. Simple washing with plain water using hoses or pressure spray equipment is usually adequate. When heavy deposits of dirt or other contaminants dull surfaces, stronger methods may be needed.

Two precautions: (1) do not use wire brushes, abrasives, or similar cleaning tools which will mechanically abrade the coatings surface, and (2) certain cleaning agents listed below should be tested in an inconspicuous area before use on a large scale.

# **GROUP A: HOT OR COLD DETERGENT SOLUTIONS**

A 5% solution in water of commonly used commercial and industrial detergents will not have any deleterious effect on a fluoropolymer surface. These solutions should be followed by an adequate rinse of water. Use a cloth or sponge for application.

# **GROUP B: SOLVENTS**

**Most organic solvents are flammable and/or toxic, and must be handled accordingly.** Read the manufacturer's Material Safety Data Sheets (MSDS). Keep away from open flames, sparks and electrical motors. Use adequate ventilation, protective clothing, and goggles.

Solvent that may be used to remove non-water soluble deposits such as tar, grease, oil, paint, and graffiti from fluoropolymer surfaces include:

#### Alcohols

- Denatured alcohol (ethanol)
- Isopropyl (rubbing alcohol)
- Methanol (wood alcohol)
  Note: methanol is toxic

The above alcohols have no permanent effect on fluoropolymer surfaces.

# GROUP C: PETROLEUM SOLVENTS AND TURPENTINE

- VM&P naphtha
- Mineral spirits
- Kerosene
- Turpentine (wood or gum spirits)

The above solvents have no permanent effect on fluoropolymer surfaces.

# **GROUP D: AROMATIC AND CHLORINATED**

- Xylol (Xylene) Toluol (Toluene)
- Perchlorethylene (Perclene)
- Tricholorethylene (Triclene)

Note: Perchlorethylene and Trichloroethylene are toxic.

The above solvents should be used with caution on a fluoropolymer surface. Limit contact with solvent to five minutes maximum and test before using.

#### GROUP E: KETONES, ESTERS, LACQUER THINNER AND PAINT REMOVER

- Methyl isobutyl ketone (MIBK)
- Ethyl acetate (nail polish remover)
- **Butyl** acetate
- Lacquer thinner
- Paint remover (non-flammable)

The above solvents should be used cautiously on a fluoropolymer surface. Limit contact to fluoropolymer surface and test before using. Note: There are many formulations of paint remover on the market. It is possible that some will remove the fluoropolymer surface. Proceed very cautiously in use of paint remover. Metal supplier and coating manufacturer are not responsible for damage from unrestricted use.

# GRAFFITI

Graffiti presents a special problem because of the many possible agents used, generally aerosol paint. It is best to try soap and water first. If needed, try the less active solvents from Groups B, C, and D. Next, try the stronger solvents in Group E. If none of these are satisfactory, it may be necessary to resort to touchup, repaint, or replacement.

#### CHEMICAL SOLUTIONS

Mildew: In areas subject to high humidity levels, dirt and spore deposits can permit mildew growth to occur. The following solution is recommended to remove mildew when necessary:

> 1/3 cup dry powdered laundry detergent (such as Tide<sup>®</sup>) 1 guart sodium hypochlorite 5% solution (such as Clorox<sup>®</sup>)

3 guarts water

Rust Stains: Hydrochloric, citric, or muriatic acid, diluted with ten volumes of water, may assist in removing rust stains from fluoropolymer surfaces. Limit contact to five minutes. Oxalic acid solutions or acetic acid (vinegar) may be used for the same purpose. Flush with water. Caution: Acid solutions are corrosive and toxic. Flush all surfaces with copious amounts of water after use.

#### WARRANTY

Misuse or abuse of any of the cleaning agents listed above will result in a voiding of warranty for the surface affected.

Valspar fluoropolymer coatings include Acroflur<sup>®</sup>, Acrodize<sup>®</sup>, Fluropon<sup>®</sup>, Fluropon Classic<sup>®</sup>, Fluropon Classic II, Fluropon Premiere, Flurothane<sup>®</sup> II, Flurothane IV, and Valflon<sup>®</sup> coatings.

# For more information, contact Valspar's Coil or Extrusion Coatings Division:

## KENTUCKY

347 Central Avenue Bowling Green, KY USA 42101 Telephone: 270.843.4831 Facsimile: 270.746.6815

Facsimile: 52.81.8360.5350

TEXAS 701 South Shiloh Road Garland TX USA 75042 Telephone: 972.276.5181 Facsimile: 972.487.7245

ILLINOIS

901 North Greenwood Avenue Kankakee, IL USA 60901 Telephone: 815.933.5561 Facsimile: 815.936.7811

0 L Ν D E Х R U S I 0 Ν С 0 Ν G S Α Т Α MEXICO CHINA CANADA BRAZIL Avenue Central 223 No. 838 Jia Xin Road 645 Coronation Drive West Hill, Ontario Los Lermas Jiading District Guadalupe, N.L. Mexico 67190 Shanghai 201818 Canada, M1E 4R6 Sao Bernardo do Campo Telephone: 52.81.8360.2020

Telephone: 416.284.1681 People's Republic of China Facsimile: 416.284.7217 Telephone: 86.21.5990.1345

Estrada dos Casa, 5050 – Portco B 09840-900 Sco Bernardo do Campo Telephone: 55.11.4358.9244 Facsimile: 55.11.4358.9228

Val#48 010828 ©The Valspar Corporation **All Rights Reserved** 

paintandcolor.com